Report for South Carolina State Hospital April 21, 1949

Building: B-21

Use: Male Patients Semi-Invalid - Elderly Rated Capacity 46; Occupancy 48

@ 20" o.ic.

I. Characteristics:

- 1. Size: 5,700 sq.ft. 1 Floor
- 2. Walls, Exterior: 12" Brick Interior: Structural Tile with Plaster
- 3. Framing: Load Brg. Walls Rafters over wards 2 x 8 @ 24" o.c.
- 4. Floors: 4" Concrete Adequate Roof: Balance of Rafters 2 x 6
- 5. Doors: Wood, o.k.
- 6. Trim: Wood, o.k. Base: Wood, Fair.
- 7. Finish: Plaster Wall & Ceiling should be Patched Before Painting
- 8. Windows: Psychiatric, o.k.
- 9. Roof: Should be Patched to Eliminate Further Damage to Walls & Ceiling.
- 10. Roof Drainage: Gutters & Downspouts, o.k.
- 11. Remarks: 2 Concrete Terraces Adaptable For Use as Day Rooms.

 They would furnish 900 sq. ft. of Additional Floor

 Space if Roofed & Enclosed.

II. Plumbing:-

	Item	Туре	Number	Condition
1.	Urinal	China	2	o.k.
2.	Water Closet	China	5	0.k.
3.	Lavatory	China	5	0.k.
4.	Shower		2	0.k.
5.	Floor Drains	2" Signet	3	o.k.
6.	Kitchen Sink		1	Bad

7. Remarks: No Floor Drains in This Building for Washing Down.

Report for South Carolina State Hospital April 21, 1949

Building: B-21

III. Electrical:-

Repairs U	rgent	Desirable
Provide Panelboard & Service Feeder	180	
Repairs to Lights & Switches, etc.	35	
Install Receptacles & Convenience Outlets	55	
Install Wiring for Instrument Sterilizer	45	
Exit Lights	235	
Increase Illumination Day Room, Dining Are	a	50
Power Wiring for Dish Washer & Sterilizer		150
	-	
	550	200

IV. Repairs:-

	Item	Urgent	Routine	Desirable
1.	Patch Plaster	\$200.		
2.	Minor Repairs to Woodwork	200.		
3.	Painting	1600.		
4.	Install Floor Drains	350.		
5.	Electrical Repairs	550		\$200.
6.	Plumbing	400		
7.	Repair Roof	400		
8.	Add Day Rooms	\$3700		\$21,000.
		\$7,400		\$21,200