

PERMANENT IMPROVEMENT SURVEY

State Hospital
(Agency)

Survey No. 26-33

Laborde B-21
(Building)

(Location)

1. Use Male Patients Semi Invalid Capacity 46 - Population 49
2. Type Construction: (a) Structure: Load Bearing Walls
(b) Exterior Walls: Brick
(c) Partition Walls: Structural Tile and Plaster
(d) Floors: Concrete (Cracked) (e) Ceiling: Plaster
(f) Roof: Wood (2" x 8")
3. No. Stories: 1 4. Floor Area: 5,700 Sq. Ft.
5. Outside Dimensions: 68'-0" x 30'-0", 68'-0" x 30'-0", 40'-0" x 52'-0"
6. Story Height: 10 Ft. 0 In. 7. Architect: _____
8. Contractor: _____ 9. Completion Date: 1929
10. Corridor Width: 8 Ft. 2 In. 11. Stairs: (a) No. None
(b) Construction _____
(c) Enclosed _____ (d) Exit to Outside _____ (e) Fire Escapes _____
12. Heating: Central Steam Plant
13. Wiring: Satisfactory
14. Plumbing: Satisfactory
15. Lighting Fixtures: Incandescent
16. Elevators: None
17. Ventilation: Adequate
18. Air Conditioning: None
19. Painting: Poor
20. Plaster: Dining Room Bad - Others Average
21. Floor Covering: Concrete

